

## Product Discontinuation Notices

Issue Date  
March 2, 2015

No. 2015026CE

Timers

**Discontinuation Notice of Option for Timer (Model PHC-2,-7,-9 and Model Y92A-Y1).**

### Product Discontinuation

### Recommended Replacement

Hook

**Model PHC-2  
(F.HOOK FOR ATSS)**

**Model PHC-7  
(L.HOOK FOR H2A)**

**Model PHC-9  
(F.HOOK FOR H2A)**

Set ring

**Model Y92A-Y1  
(SET RING FOR H3BA ETC)**



**No recommended replacement**


### [ Discontinuation date ]

The end of March, 2016

### [ Product Discontinuation and recommended replacement ]

Product discontinuation	Recommended replacement
PHC-2 (F.HOOK FOR ATSS)	No recommended replacement
PHC-7 (L.HOOK FOR H2A)	No recommended replacement
PHC-9 (F.HOOK FOR H2A)	No recommended replacement
Y92A-Y1 (SET RING FOR H3BA ETC)	No recommended replacement

### [ Dimensions ]



**Product discontinuation  
Model PHC-7**

This is the hook for the Model H2A.

There is no image.

Note) Model H2A of timer body has finished production in March 2007.

**Product discontinuation  
Model PHC-9**


This is the hook for the Model H2A.

There is no image.

Note) Model H2A of timer body has finished production in March 2007.

**Product discontinuation  
Model Y92A-Y1**

This is an optional product to set highly reproducible times.  
It can be used to fit the set ring into the time adjustor.



Note) Model H2C of timer body has finished production in March 2013.  
Model H3B of timer body has finished production in March 2007.

Specifications and prices in this product news are as of the issue date and are subject to change without notice.  
Only main changes in specifications are described in this document. Please be sure to read the relevant catalogs, datasheets, product specifications, instructions, and manuals for precautions and necessary information when using products.